











# SUMMER CARE

front view | bottom view



No.									
HD 13212	30	35	86	88,9	31	31	8,8	GPI 18/400	SKIN CARE PUMP OVERCAP HP 6188